


# DRIP

## Neomodern Glass Sphere Pendant Luminaire



### Installation Steps:

Step ①: Twist to install the crystal.

Step ② ③ ④ ⑤: Lead the DC cable of LED engine through stems all the way to mounting bracket, fasten tightly each stems and the swivel ball.

Step ⑥: Connect the DC cable to the driver output.

Step ⑦: Fasten the mounting bracket to J-box.

Step ⑧: Connect the AC cable to the power lead (Black to Line, White to Neutral and green to ground).

Step ⑨: Fasten the two screws of canopy to the mounting bracket.

